

AIR MONITORING FIELD DATA SHEET  
CENTURY MODEL 128 ORGANIC VAPOR ANALYZER  
(FLAME IONIZATION DETECTOR)

INCIDENT NAME: BOSSERT MFG.

INCIDENT LOCATION: 1002 OSWEGO ST.

UTICA, NEW YORK

DATE AND TIME OF INITIAL ARRIVAL: 8/25/87 9:20

WEATHER CONDITIONS: Temperature 63 Pressure \_\_\_\_\_

Wind Speed \_\_\_\_\_ Wind Direction \_\_\_\_\_ Humidity \_\_\_\_\_

General Weather Conditions Clear, Sunny

OVA CALIBRATION DATA: EPA ID # 190017 Mode \_\_\_\_\_

Date Calibrated By Factory \_\_\_\_\_

Are there any potential interferences (i.e. high winds, electrical wires, chemical interferences, 2-way radios, pressure drop, etc.)  
Comments: Results are report as part per million methane

equivalent.

BACKGROUND LOCATION: Decon Shed

Time: 920 Reading: 2.0 Comments: \_\_\_\_\_

SAMPLING LOCATION: Area 8 & 9

Time: \_\_\_\_\_ Reading: 3.5 Comments: \_\_\_\_\_

SAMPLING LOCATION: Area #12

Time: \_\_\_\_\_ Reading: 3.0 Comments: \_\_\_\_\_

SAMPLING LOCATION: Sump #15 & 6 over sump

Time: \_\_\_\_\_ Reading: 3.8 Comments: Pumping out sump with skid unit.

SAMPLING LOCATION: Sump # 3

Time: \_\_\_\_\_ Reading: 5.0 Comments: NO Activity

SAMPLING LOCATION: \_\_\_\_\_

Time: \_\_\_\_\_ Reading: \_\_\_\_\_ Comments: \_\_\_\_\_



AIR MONITORING FIELD DATA SHEET  
CENTURY MODEL 128 ORGANIC VAPOR ANALYZER  
(FLAME IONIZATION DETECTOR)

INCIDENT NAME: BOSSERT MFG.

INCIDENT LOCATION: 1002 OSWEGO ST.  
UTICA, NEW YORK

DATE AND TIME OF INITIAL ARRIVAL: 8/25/87 1530

WEATHER CONDITIONS: Temperature 71 Pressure \_\_\_\_\_  
Wind Speed \_\_\_\_\_ Wind Direction \_\_\_\_\_ Humidity \_\_\_\_\_  
General Weather Conditions SUNNY CLEAR

OVA CALIBRATION DATA: EPA ID # 196017 Mode \_\_\_\_\_  
Date Calibrated By Factory \_\_\_\_\_

Are there any potential interferences (ie. high winds, electrical wires, chemical interferences, 2-way radios, pressure drop, etc.)  
Comments: Results are report as part per million methane equivalent.

BACKGROUND LOCATION: Decon Shed

Time: 1540 Reading: 2.0 Comments: \_\_\_\_\_

SAMPLING LOCATION: Area # 18+9

Time: \_\_\_\_\_ Reading: 2.5 Comments: \_\_\_\_\_

SAMPLING LOCATION: Area # 12

Time: \_\_\_\_\_ Reading: 2.5 Comments: \_\_\_\_\_

SAMPLING LOCATION: SDR Pool Area 3

Time: \_\_\_\_\_ Reading: 2.5 Comments: \_\_\_\_\_

SAMPLING LOCATION: Sump # 1 MAN IN Sump

Time: \_\_\_\_\_ Reading: 4.5 Comments: Sludge out of sump

SAMPLING LOCATION: Sump # 3 MAN IN Sump

Time: \_\_\_\_\_ Reading: 20.0 Comments: Generator nearby